

	Type	L #	Hits	Search Text	DBs	Time Stamp	Components	Error Correction	Errors
1	BRS	L51 1	0	"road surface" same sound-absorb ing same material	USPAT; EPO; JPO; DERWEN T	2003/01/22 10:57		n	0
2	BRS	L51 2	10	"road surface" same sound same (absorbing or absorption) same material	USPAT; EPO; JPO; DERWEN T	2003/01/22 10:58			0
3	BRS	L51 3	3	concrete same rail same sound same (absorption or absorbing) same (material or layer)	USPAT	2003/01/22 11:01			0

		Type	L #	Hits	Search Text	DBs	Time Stamp	Cor re ct o r m e n t s	Err or s for m e n t i o n
1	BRS	L2	874		"rail seat"	USPAT; EPO; JPO; DERWEN T	2003/01/22 07:33		0
2	BRS	L3	874		"rail seat"	USPAT; EPO; JPO; DERWEN T	2003/01/22 08:02		0
3	BRS	L6	19		104/143	USPAT; EPO; JPO; DERWEN T	2003/01/22 08:07		0
4	BRS	L7	208		238/264	USPAT; EPO; JPO; DERWEN T	2003/01/22 08:08		0
5	BRS	L9	0		238/DIG1	USPAT; EPO; JPO; DERWEN T	2003/01/22 08:09		0
6	BRS	L4	539		238/283	USPAT; EPO; JPO; DERWEN T	2003/01/22 08:10		0

	Type	L #	Hits	Search Text	DBs	Time Stamp	Errors
							Correlation Definition
7	BRS	L5	282	238/382	USPAT; EPO; JPO; DERWEN T	2003/01/22 08:38	0